












































































DHAKA WASA



LIT, PIT, FIT REPORT – NOVEMBER 2023

DTW No.	LIT	PIT	FIT	REMARKS
101				PIT works but display problem. Need to change FIT connection terminal box. (02.11.2023)
102				LIT is stucken in flexible pipe. Need to change FIT connection terminal box. (02.11.2023)
103				Need to change FIT connection terminal box. (02.11.2023)
104				LIT is stucken in flexible pipe. Need to change FIT connection terminal box. (04.11.2023)
105				LIT damage. LIT is stucken in flexible pipe. Need to change FIT connection terminal box. (04.11.2023)
106				LIT is stucken in flexible pipe. (04.11.2023)
107				Need to change FIT connection terminal box. (04.11.2023)
109				
110				Need to change FIT connection terminal box. LIT is stucken in flexible pipe. (05.11.2023)
111				Need to change FIT connection terminal box. LIT is stucken in flexible pipe. (05.11.2023)
112				

DTW No.	LIT	PIT	FIT	REMARKS
116	✓	✓	✓	Okay
117	✓	✓	✓	LIT is stucken in flexible pipe.
118	✓	✓	✓	Okay
119	✓	✓	✓	LIT is stucken in flexible pipe.
120	✓	✓	✓	LIT is stucken in flexible pipe.
121	✓	✓	✓	Okay
122	✓	✓	✓	Okay
123	✗	✓	✓	LIT damaged. LIT is stucken in flexible pipe.
201	✓	✓	✓	Okay
202	✓	✓	✓	Okay
203	✓	✓	✓	Okay
204	✓	✓	✓	Okay
205	✓	✓	✓	Okay
206	✓	✓	✓	Okay
207				Rehabilitation work on going. SCADAPack U/A
208	✓	✓	✓	Okay

DTW No.	LIT	PIT	FIT	REMARKS
209				Okay
210				PLC U/A
211				Okay
212				Okay
213				Okay
214				PLC serial port, PIT, LIT ,SPD damaged by thundering . LIT is stucken in flexible pipe.
215				Okay
216				Okay
217				Okay
218				Okay
219				LIT damaged. LIT is stucken in flexible pipe.
220				Okay
221				LIT damaged. LIT is stucken in flexible pipe.
222				Okay
223				Okay