

# SAVAR-KERANIGANJ WELL FIELD PLANT

CCTV MAINTENANCE REPORT – January,2024

SL. No.	DTW No./Camera	Problem Findings	Maintenance	Remarks
01	201/1	Cable damage.	UTP cable core interchange.	5 Nos cameras are operational.
02	205/1	Cable & camera damage.	7M UTP cable use & install 1 Nos new camera.	5 Nos cameras are operational.
03	207/2	Cable & camera damage.	UTP cable core interchange & install 2 Nos new camera.	5 Nos cameras are operational.
04	209/2	Cable damage.	UTP cable core interchange.	5 Nos cameras are operational.
05	206/2	Cable damage & 1 Nos camera has internal problem.	UTP cable core interchange. install 1 Nos new camera.	5 Nos cameras are operational.
06	222/5	ONU internal problem.	Clean & reset.	5 Nos cameras are operational.
07	208/1	Cable damage.	UTP cable core interchange. 20M UTP cable use	5 Nos cameras are operational.
08	202/1	Cable damage.	23M UTP cable use.	5 Nos cameras are operational.
09	211/2	Cable damage.	UTP cable core interchange & 21M UTP cable use.	5 Nos cameras are operational.
10	212/2	Cable damage.	UTP cable core interchange & 16M UTP cable use.	5 Nos cameras are operational.
11	219/1	Cable damage.	7M UTP cable use.	5 Nos cameras are operational.

12	215/1	Camera damage.	install 1 Nos new camera.	5 Nos cameras are operational.
13	216/1	Camera damage.	install 1 Nos new camera.	5 Nos cameras are operational.
14	101/1	Cable damage.	UTP cable core interchange.	5 Nos cameras are operational.
15	102/1	Cable damage.	UTP cable core interchange.	5 Nos cameras are operational.
16	106/1	Camera damage.	7M UTP cable use & install 1 Nos new camera.	5 Nos cameras are operational.
17	IRP-1 Front Gate	Cable damage & 1 Nos camera has internal problem.	23M UTP cable use & maintenance the camera.	Camera is operational.
18	206/1	1 Nos camera has internal problem.	install 1 Nos new camera.	5 Nos cameras are operational.
19	213/1	UTP connector damage found.	Change UTP connector.	5 Nos cameras are operational.
20	208/1	Cable damage.	20M UTP cable use	
21	202/1	Cable damage.	23M UTP cable use	
22	120/1	PoE port problem, camera is okay.	Need to change PoE switch.	4 Nos cameras are operational.
23				

- For maintenance whole problems, we have been required 7 Nos new camera & 167M UTP cable.

- Status:
 

NAV-1: Total camera: 56 Nos	Active camera: 56 Nos	Unactive camera: 00 Nos
NAV-2: Total camera: 56 Nos	Active camera: 55 Nos	Unactive camera: 01 Nos
NAV-3: Total camera: 61 Nos	Active camera: 61 Nos	Unactive camera: 00 Nos
NAV-4: Total camera: 61 Nos	Active camera: 61 Nos	Unactive camera: 00 Nos